

**National Transportation Safety Board  
Washington, DC 20594**

**Brief of Accident**

**Adopted 11/25/2003**

IAD02LA080		08/01/2002		Patuxent River, MD		Aircraft Reg No. N1177M		Time (Local): 14:20 EDT					
Make/Model: Cessna / 172K						Fatal		Serious		Minor/None			
Engine Make/Model: Lycoming / O-320						Crew		0		1		0	
Aircraft Damage: Substantial						Pass		0		0		1	
Number of Engines: 1													
Operating Certificate(s): None													
Type of Flight Operation: Personal													
Reg. Flight Conducted Under: Part 91: General Aviation													
Last Depart. Point: Myrtle Beach, SC								Condition of Light: Day					
Destination: Same as Accident/Incident Location								Weather Info Src: Weather Observation Facility					
Airport Proximity: On Airport								Basic Weather: Visual Conditions					
Airport Name: Patuxent River NAS								Lowest Ceiling: None					
Runway Identification: 06								Visibility: 7.00 SM					
Runway Length/Width (Ft): 11809 / 200								Wind Dir/Speed: 040 / 009 Kts					
Runway Surface: Grass/turf								Temperature (°C): 34					
Runway Surface Condition: Dry								Precip/Obscuration: None / None					
Pilot-in-Command		Age: 28						Flight Time (Hours)					
Certificate(s)/Rating(s)								Total All Aircraft: 815					
Commercial; Single-engine Land; Helicopter								Last 90 Days: 46					
Instrument Ratings								Total Make/Model: 9					
Airplane; Helicopter								Total Instrument Time: UnK/Nr					

Prior to his departure, the pilot performed a preflight inspection and determined the fuel onboard the airplane by observing the fuel gauges in the cockpit. The gauges indicated the fuel tanks were about 1/4 - 1/2 full, or 8 gallons of fuel per tank. The pilot stated he did not visually check the fuel tanks because he did not have a way to measure the fuel. The pilot added 20 additional gallons of fuel, for a total of 36 gallons of fuel onboard, which he estimated to be 4 1/2 hours flight time. After fueling the airplane, the fuel gauges read about 3/4 full on each tank. The pilot flew direct to his destination; however, he did not perform any fuel burn calculations en route. Approximately 3 miles from the airport, the airplane's engine lost power. The pilot checked the fuel gauges, which indicated 1/8 full on the left side and 1/4 full on the right side. He unsuccessfully attempted to restart the engine, and performed a forced landing approximately 1/2 mile short of the runway. Examination of the airplane revealed that the left wing tank was completely empty and 1/8 inch of fuel remained in the right wing tank. The airplane's fuel system was examined and no pre-impact anomalies were noted. A test run of the engine was performed on the airframe, and it started without hesitation and ran continuously through a variety of power settings. An accurate test of the fuel level transmitters and fuel gauges was unable to be performed during the initial examination, because they were removed and retained by the operator. The pilot had accumulated 124 hours of fixed-wing flight experience, 9 of which were in make and model, and 691 hours in rotorcraft.

Brief of Accident (Continued)

IAD02LA080  
File No. 14278                      08/01/2002                      Patuxent River, MD                      Aircraft Reg No. N1177M                      Time (Local): 14:20 EDT

---

Occurrence #1:      LOSS OF ENGINE POWER  
Phase of Operation: APPROACH

Findings

1. FLUID,FUEL - EXHAUSTION
  2. (C) FUEL SUPPLY - INADEQUATE - PILOT IN COMMAND
  3. (C) FUEL CONSUMPTION CALCULATIONS - INADEQUATE - PILOT IN COMMAND
- 

Occurrence #2:      FORCED LANDING  
Phase of Operation: DESCENT - EMERGENCY

-----

Occurrence #3:      IN FLIGHT COLLISION WITH TERRAIN/WATER  
Phase of Operation: EMERGENCY DESCENT/LANDING

Findings

4. TERRAIN CONDITION - GROUND
- 

Occurrence #4:      GEAR COLLAPSED  
Phase of Operation: EMERGENCY LANDING

Findings Legend: (C) = Cause, (F) = Factor

---

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.  
The pilot's inadequate fuel calculations, which resulted in fuel exhaustion and a subsequent loss of engine power.